

<b>OWNER:</b>	POLISH AIR MEDICAL RESCUE / LOTNICZE POGOTOWIE RATUNKOWE	<b>OPERATOR:</b>	POLISH AIR MEDICAL RESCUE / LOTNICZE POGOTOWIE RATUNKOWE
<b>ADDRESS:</b>	KSIEZYCOWA 5 WARSZAWA 01-934	<b>ADDRESS:</b>	KSIEZYCOWA 5 WARSZAWA 01-934
<b>PHONE:</b>	+48 (22) 22-99-931	<b>PHONE:</b>	+48 (22) 22-99-931
<b>FAX:</b>		<b>FAX:</b>	
<b>ANALYST:</b>	MAXIME MOREAU	+33-1.55.93.47.74 (DIRECT)	PLEASE RECORD CHANGES TO ADDRESS, LAST
<b>EMAIL:</b>	MAXIME.MOREAU@CAMPSYSTEMS.EU	+33 (0) 1.55.93.45.80 (OFFICE)	ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO
		WWW.CAMPSYSTEMS.COM	CAMP.

**Filter Criteria:** ATA From: 70 - To: 81; Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

<b>AIRCRAFT</b>	<b>SERIAL/REGNO:</b> 1079/SP-MXH	<b>MODEL:</b> PIAGGIO P180 AVANTI EASA.A.059	<b>MANUFACTURER:</b> PIAGGIO AEROSPACE
-----------------	----------------------------------	--	--

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 22-APR-2004	5611:59 A/C HRS as of 13-SEP-2020	A/C HRS as of ____/____/____
	8577 AFL as of 13-SEP-2020	AFL as of ____/____/____

<b>ENGINE NO. 1</b>	<b>SERIAL/PART:</b> PCE-RK0104/3037000	<b>MODEL:</b> PT6A-66	<b>MANUFACTURER:</b> PRATT & WHITNEY CANADA CORP.
---------------------	--	-----------------------	---

INSTALLED ON 21-JUL-2014	LAST ACTUALS	CURRENT ACTUAL
3816:24 ENG. HRS 4076:57 A/C HRS	5349:25 ENG. HRS as of 13-SEP-2020	ENG. HRS as of ____/____/____
5018 ENC	7229 ENC as of 13-SEP-2020	ENC as of ____/____/____

<b>ENGINE NO. 2</b>	<b>SERIAL/PART:</b> PCE-RK0103/3037000	<b>MODEL:</b> PT6A-66	<b>MANUFACTURER:</b> PRATT & WHITNEY CANADA CORP.
---------------------	--	-----------------------	---

INSTALLED ON 13-JAN-2015	LAST ACTUALS	CURRENT ACTUAL
4090:59 ENG. HRS 4183:03 A/C HRS	5519:55 ENG. HRS as of 13-SEP-2020	ENG. HRS as of ____/____/____
5396 ENC	7348 ENC as of 13-SEP-2020	ENC as of ____/____/____

<b>PROPELLER NO</b>	<b>SERIAL/PART:</b> KU85E/HC-E5N-3A	<b>MODEL:</b> HC-E5N-3	<b>MANUFACTURER:</b> HARTZELL PROPELLER INC.
---------------------	-------------------------------------	------------------------	--

INSTALLED ON 03-JUN-2019	LAST ACTUALS	CURRENT ACTUAL
5597:18 PROP HRS 5156:54 A/C HRS	6120:16 PROP HRS as of 13-SEP-2020	PROP HRS as of ____/____/____

<b>PROPELLER NO</b>	<b>SERIAL/PART:</b> HF217E/HC-E5N-3AL	<b>MODEL:</b> HC-E5N-3	<b>MANUFACTURER:</b> HARTZELL PROPELLER INC.
---------------------	---------------------------------------	------------------------	--

INSTALLED ON 03-JUN-2019	LAST ACTUALS	CURRENT ACTUAL
5549:53 PROP HRS 5156:54 A/C HRS	6072:39 PROP HRS as of 13-SEP-2020	PROP HRS as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - AD - 1079/SP-MXH</b>							
EASA 2010-0123	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT					SUPERSEDED	COMPLIED WITH
06-JUL-2010		MOS HRS/MSC - AFL		29-NOV-2011 3319:59 5183			
EASA 2010-0123 R01	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - CANCELLED DUE TO DIPSTICK HAS BEEN CHANGED FOR NEW ONE WHERE THIS INSPECTION IS N/A. IAW AD NO MORE ACTION IS REQUIRED.
		MOS HRS/MSC - AFL		09-AUG-2013 3836:53 5941			
EASA 2010-0125 PART (1)	OIL - OIL COOLING SYSTEM HOSE - INSPECTION						COMPLIED WITH - CLOSED
		MOS HRS/MSC - AFL		05-JUN-2018 4823:15 7386			
ENAC 1993-034	HEAT EXCHANGER EXHAUST GAS/HEATING AIR FOR COCKPIT AND PASSENGER CABIN.						NOT APPLICABLE - BY EFFECTIVITY
15-MAR-1993		MOS HRS/MSC - AFL		22-APR-2004 0 0			
ENAC 1995-087	ENGINE POWER AND PROPELLER CONTROLS - WATER PROTECTION						NOT APPLICABLE
		MOS HRS/MSC - AFL		22-APR-2004 0 0			
ENAC 2002-335 PART (A)	OIL COOLING SYSTEM - INSPECTION CHECK.					SUPERSEDED	COMPLIED WITH
		MOS HRS/MSC - AFL		30-AUG-2016 4685:51 7191			
ENAC 2002-335 PART (B)	OIL COOLING SYSTEM - INSPECTION CHECK.					SUPERSEDED	COMPLIED WITH
		MOS HRS/MSC - (s) AFL		15-NOV-2008 1995:52 2995			
ENAC 2010-215	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT -					MANDATORY	COMPLIED WITH
23-JUN-2010		MOS HRS/MSC - AFL		03-JAN-2011 3000:47 4719			
ENAC 2010-220 PART (1)	OIL - OIL COOLING SYSTEM HOSE - INSPECTION					MANDATORY	COMPLIED WITH
		MOS HRS/MSC - AFL		05-JUN-2018 4823:15 7386			
ENAC 2011-353	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - CANCELLED DUE TO DIPSTICK HAS BEEN CHANGED FOR NEW ONE WHERE THIS INSPECTION IS N/A. IAW AD NO MORE ACTION IS REQUIRED.
		MOS HRS/MSC - AFL		09-AUG-2013 3836:53 5941			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - SB - 1079/SP-MXH</b>							
SB 80-0022	MODIFIED EXHAUST STACKS - INSTALLATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		22-APR-2004			
06-JUL-1992		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0027	MAGNETIC CHIP DETECTOR INDICATION - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		22-APR-2004			
12-MAY-1992		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0040	POWER LEVER "GO-AROUND" AND "GEAR MUTE" SWITCHES - CHANGE OF THEIR MUTUAL POSITIONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		22-APR-2004			
20-MAY-1993		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0066	POWER AND PROPELLER CONTROLS - WATER PROTECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		22-APR-2004			
12-DEC-1994		HRS/MSC	-	0			
		AFL		0			
SB 80-0080	PROPELLER LOW PITCH STOP SWITCH - MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		22-APR-2004			
03-JUL-1995		HRS/MSC	-	0			
		AFL		0			
SB 80-0092	PLENUM ZONE MODIFICATION IN CASE OF INSTALLATION OF ENGINES EQUIPPED WITH IMPROVED BLEED OFF VALVES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS		22-APR-2004			
14-APR-1997		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0129	CENTER AND REAR FIREWALLS MODIFICATION FOLLOWING ENGINE MODIFICATION AS PER LAST ISSUE OF PRATT & WHITNEY CANADA S.B. NO.14308, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		22-APR-2004			
22-SEP-2000		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0145	P/N 80-336013-403 EXHAUST STACKS - INSPECTION/REPAIR AS NECESSARY, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS		30-JAN-2008			
17-JUN-2005		HRS/MSC	-	1555:36			
		AFL		2308			
SB 80-0145 REV.1	P/N 80-336013-403 EXHAUST STACKS - INSPECTION/REPAIR AS NECESSARY, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - ALREADY CW IAW PREVIOUS REVISION
		MOS		12-DEC-2011			
02-DEC-2011		HRS/MSC	-	3340:19			
		AFL		5212			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 80-0145 REV.2	P/N 80-336013-403 EXHAUST STACKS - INSPECTION / REPAIR / REPLACEMENT AS NECESSARY, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE - N/A DUE TO COMPLETED REV. 0 OF THIS SB. SEE SCE 1178/1124 FROM 30.01.2008. NO ACTION REQUIRED FOR OPERATORS WHO PERFORMED PREVIOUS ISSUE OF THIS SB.
29-MAR-2013		MOS HRS/MSC - AFL		17-APR-2013 3805:01 5891			
SB 80-0145 REV.3	P/N 80-336013-403 EXHAUST STACKS - INSPECTION / REPAIR / REPLACEMENT AS NECESSARY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS HRS/MSC - AFL		05-JUN-2018 4823:15 7386			
SB A 80-0175 REV 01 PART	OIL COOLING SYSTEM TUBING INSTALLATION CLEARANCE FROM THE ENGINE MOUNTED OIL-TO-FUEL HEATER - INSPECTION CHECK, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - CLOSED
		MOS HRS/MSC - AFL		05-JUN-2018 4823:15 7386			
SB B 80-0175 REV 01 PART	OIL COOLING SYSTEM TUBING INSTALLATION CLEARANCE FROM THE ENGINE MOUNTED OIL-TO-FUEL HEATER - INSPECTION CHECK, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
14-MAY-2010		MOS HRS/MSC A/R (s) AFL		05-JUN-2018 4823:15 7386			
SB 80-0194	CHIP DETECTOR MONITORING SYSTEM - INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
26-MAY-2004		MOS HRS/MSC A/R AFL		26-MAY-2004			
SB 80-0287	ENGINE OIL LEVEL CHECK, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
12-OCT-2009		MOS HRS/MSC - AFL		25-MAR-2010 2663:54 4202			
SB 80-0287 REV.1	ENGINE OIL LEVEL CHECK, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
24-MAR-2010		MOS HRS/MSC - AFL		22-NOV-2011 3300:14 5156			
SB 80-0287 REV.2	ENGINE OIL LEVEL CHECK, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - CANCELLED DUE TO DIPSTICK HAS BEEN CHANGED FOR NEW ONE WHERE THIS INSPECTION IS N/A. IAW AD NO MORE ACTION IS REQUIRED.
		MOS HRS/MSC - AFL		09-AUG-2013 3836:53 5941			
SB 80-0315	THROTTLE QUADRANT -MICROSWITCHES LEVERS IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
09-MAR-2011		MOS HRS/MSC - AFL		03-JUN-2011 3026:56 4753			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 80-0421	REPLACEMENT OF ENGINE OIL HOSE ASSY (OIL COOLER TO ENGINE), SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE - DUE TO MSN
16-NOV-2017		HRS/MSC -					
		AFL					
SB 80-0421 PART A	ACCOMPLISH REPLACEMENT OF ENGINE OIL HOSE ASSY (OIL COOLER TO ENGINE), SERVICE BULLETIN REMOVAL OF UPPER AND LOWER NACELLES; OIL COOLING SYSTEM INSPECTION; INSTALLATION OF UPPER AND LOWER NACELLES	MOS				RECOMMENDED	NOT APPLICABLE - DUE TO MSN
16-NOV-2017		HRS/MSC -					
		AFL					
SB 80-0421 PART B	ACCOMPLISH REPLACEMENT OF ENGINE OIL HOSE ASSY (OIL COOLER TO ENGINE), SERVICE BULLETIN INSTALLATION OF THE NEW HOSE ASSY P/N 80-337283-001 AND FITTING P/N 80-337290-001 (FOR LH ENGINE ONLY) (FOLLOWING INSPECTION FINDINGS IAW PART A OF THIS SB)	MOS				RECOMMENDED	NOT APPLICABLE - DUE TO MSN
16-NOV-2017		HRS/MSC - (s)					
		AFL					
SB 80-0440	INSPECTION OF PROPELLER CONTROL CAM ASSEMBLY, SERVICE BULLETIN	MOS		12-OCT-2015		SUPERSEDED	NOT APPLICABLE - N/A DUE TO MSN
30-OCT-2015		HRS/MSC -		4411:10			
		AFL		6783			
SB 80-0440 PART A	VISUAL INSPECTION INSPECTION OF PROPELLER CONTROL CAM ASSEMBLY, SERVICE BULLETIN OF PROPELLER CONTROL CAM ASSEMBLY	MOS		12-OCT-2015		SUPERSEDED	NOT APPLICABLE - N/A DUE TO MSN
30-OCT-2015		HRS/MSC -		4411:10			
		AFL		6783			
SB 80-0440 PART B	REWORK INSPECTION OF PROPELLER CONTROL CAM ASSEMBLY, SERVICE BULLETIN OF THE WASHER P/N NAS1149C0316R	MOS		12-OCT-2015		SUPERSEDED	NOT APPLICABLE
30-OCT-2015		HRS/MSC -		4411:10			
		AFL		6783			
SB 80-0442	INSPECTION/REPAIR OF P180 LH WING - INTERFERENCE BETWEEN HOSE P/N 3112402-01 OR 3108703-01 AND REAR SPAR FIREWALL P/N 80-336061-007, SERVICE BULLETIN	MOS		05-JUN-2018		RECOMMENDED	COMPLIED WITH
18-DEC-2015		HRS/MSC -		4823:15			
		AFL		7386			
SB A 80-0455 REV 01 PART A	ACCOMPLISH INSPECTION OF P180 AVANTI/AVANTI II - FORWARD WING FLAP, AILERON, MAIN WING INBOARD FLAP AND ELEVATOR ASSEMBLIES, SERVICE BULLETIN IDENTIFICATION OF FLIGHT CONTROL SURFACES SERIAL NUMBERS, ACCORDING TO AIRCRAFT'S LOGBOOK AND CHECK IF THE IDENTIFIED PARTS ARE INCLUDED IN THE NOT-AFFECTED UNITS LIST AS PER 1.A. TABLE 1 OF THIS SERVICE BULLETIN (IF ONE OR MORE SURFACE(S) IS (ARE) NOT LISTED IN 1.A. TABLE 1, PROCEED WITH PART B OR C OF THIS SERVICE BULLETIN FOR THIS(THESE) SURFACE(S), OTHERWISE NO OTHER ACTIONS ARE REQUIRED)	MOS		05-JUN-2018		MANDATORY	COMPLIED WITH
30-MAR-2017		HRS/MSC -		4823:15			
		AFL		7386			
SB 80-0461	P180 ENGINE MOUNTS AND ENGINE MOUNTS ELECTRICAL BONDING CONNECTIONS - CHECK, SERVICE BULLETIN	MOS		22-APR-2004		MANDATORY	
25-JAN-2018		HRS/MSC -					
		AFL					

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**

**All Bulletins with Compliance or Due**

**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 80-0480	INSPECTION OF PROPELLER REVERSING LEVER AND GUIDE PIN INSTALLATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - DUE TO ENGINES, PROPELLERS, PROPELLER GOVERNORS AND PROPELLER BETA RINGS HAS NOT BEEN REPLACED IN THE LAST 150 FH
08-APR-2020		MOS HRS/MSC - AFL			10-APR-2020		

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 15-Sep-2020

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - PCE-RK0104/3037000							
FAA 2012-09-10	NO. 1 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLER REDUCTION GEARBOX ASSEMBLY					MANDATORY	NOT APPLICABLE - N/A DUE TO DIFFERENT P/N OF PARTS INSTALLED ON 1079, LISTED IN SUBJECT AD.
		MOS		11-MAY-2012			
		HRS/MS	-	3524:37			
		AFL					
		ENC		4581			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 15-Sep-2020

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - PCE-RK0103/3037000							
FAA 2012-09-10	NO. 2 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLER REDUCTION GEARBOX ASSEMBLY					MANDATORY	COMPLIED WITH
		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
LBA D-2012-210	NO. 2 ENGINE - TURBINE ENGINE -TIMKEN ALCOR AEROSPACE TECHNOLOGIES, INC. FIRST STAGE SUN GEARS AND PLANET GEARS - REMOVAL FROM SERVICE					MANDATORY	COMPLIED WITH
		MOS		23-DEC-2012			
		HRS/MSC - (s)		3706:50			
		ENC		4821			



Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - SB - PCE-RK0104/3037000</b>							
ASB PT6A-72-A14410	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
06-SEP-2007		MOS HRS/MSC - ENC		20-SEP-2007			
ASB PT6A-72-A14410 R1	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
20-SEP-2007		MOS HRS/MSC - ENC		20-SEP-2007			
ASB PT6A-72-A14410 R2	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN						NOT APPLICABLE
18-FEB-2014		MOS HRS/MSC - ENC		07-MAR-2014 3854:38 5015			
SB PT6A-72-14001 R16	NO. 1 ENGINE - TURBOPROP ENGINE APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH - INFORMATION ONLY REGARDING THE APPROVED USING OILS.
20-MAR-2015		MOS HRS/MSC - ENC		11-SEP-2015 4148:36 5566			
SB PT6A-72-14002 R21	NO. 1 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
12-DEC-2011		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14002 R22	NO. 1 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
16-NOV-2012		MOS HRS/MSC - ENC		29-MAY-2013			
SB PT6A-72-14015 R2	NO. 1 ENGINE - REPLACEMENT OF NEW COMPRESSOR TURBINE BOLT, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N DOESN'T MEET REQUIREMENTS OF SB
16-DEC-2014		MOS HRS/MSC - ENC		12-DEC-2014 5222			
SB PT6A-72-14048 R3	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INNER AND OUTER COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ESN
		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14061 R2	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SECTION, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
23-JUN-1993		MOS HRS/MSC N/R (s) ENC		03-FEB-2004 0 0			
SB PT6A-72-14089 R1	NO. 1 ENGINE - INTRODUCTION OF IMPROVED HIGHER LOAD BEARING CAPACITY CONFIGURATION NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - DUE TO ESN
12-MAR-2010		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14109 R1	NO. 1 ENGINE - TURBOPROP ENGINE COMPRESSOR ROTOR SHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - DUE TO ESN
14-MAY-2008		MOS HRS/MSC ENC	A/R	21-DEC-2012 3612:25 4722			
SB PT6A-72-14142 R3	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE BLADE WITH FEATHER SEALS, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ESN
17-SEP-2008		MOS HRS/MSC ENC	-	21-DEC-2012 3612:25 4722			
SB PT6A-72-14144 R2	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE (CT) STATOR ASSEMBLY, CT SHROUD HOUSING, SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ESN
01-APR-2008		MOS HRS/MSC ENC	-	21-DEC-2012 3612:25 4722			
SB PT6A-72-14162 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO AFFECTED PROPELLER GOVERNOR P/NS ARE NOT INSTALLED ON ENGINES
09-APR-2018		MOS HRS/MSC ENC	-	12-APR-2018			
SB PT6A-72-14269 R5	NO. 1 ENGINE - REPLACEMENT OF P3 AIR PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N
01-MAR-2015		MOS HRS/MSC ENC	-	23-MAR-2015 4042:58 5423			
SB PT6A-72-14270 R1	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO POST SB 14067
13-MAY-1998		MOS HRS/MSC ENC	N/R (s)	21-DEC-2012 3612:25 4722			
SB PT6A-72-14274 R1	NO. 1 ENGINE - PT6A-66 MINIMUM STANDARD CONFIGURATION REQUIREMENT TO UPGRADE HOT SECTION COMPONENTS, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
03-NOV-2009		MOS HRS/MSC ENC	-	21-DEC-2012 3612:25 4722			
SB PT6A-72-14275 R2	NO. 1 ENGINE - REPLACEMENT OF OIL FILLER CAP AND LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
13-JUN-2011		MOS HRS/MSC ENC	-	21-DEC-2012 3612:25 4722			
SB PT6A-72-14301 R2	NO. 1 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART NUMBER
03-FEB-2010		MOS HRS/MSC ENC	-	21-DEC-2012 3612:25 4722			
SB PT6A-72-14308 R3	NO. 1 ENGINE - REPLACEMENT OF REDUCTION GEARBOX SCAVENGE LINE, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
04-OCT-2011		MOS HRS/MSC ENC	-	21-DEC-2012 3612:25 4722			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14317 R3	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF INNER AND OUTER LINER, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART SN AND ESN
14-DEC-2010		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14329 R4	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PREVIOUSLY EMBODIED
30-APR-2010		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14346 R2	NO. 1 ENGINE - INTRODUCTION OF NO.2 BEARING OIL NOZZLE WITH RETAINING RING, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART ESN
06-MAY-2011		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14357 R4	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS HRS/MSC - ENC		08-JUL-2014 3816:24 5018			
SB PT6A-72-14365 R1	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - RK0104 HAS INSTALLED SB 14364. WHEN SB 14364 HAS BEEN INSTALLED, SB 14365 IS N/A
08-JAN-2013		MOS HRS/MSC - ENC		03-MAR-2013 3660:46			
SB PT6A-72-14376	NO. 1 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A - THIS SB IS N/A FOR ENGINE PCE-RK0104 DUE TO PARKER FUEL PUMP INSTALLED ON THE ENGINE (NOT SUNSTAND AS SB REFER)
17-AUG-2012		MOS HRS/MSC - ENC		03-MAR-2013 3660:46			
SB PT6A-72-14376 R1	NO. 1 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
22-OCT-2013		MOS HRS/MSC - ENC		16-OCT-2014 5208			
SB PT6A-72-14377 R01	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, SERVICE BULLETIN						DEFERRED
26-AUG-2015		MOS HRS/MSC - ENC		27-AUG-2015 4148:36 5566			
SB PT6A-72-14383	NO. 1 ENGINE - REPAIR OF FILLER CAP AND ELECTRIC OIL LEVEL DIPSTICK, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
26-FEB-2010		MOS HRS/MSC - ENC		10-APR-2010 2663:54 3498			
SB PT6A-72-14395 R3	NO. 1 ENGINE - BOLTS AND NUTS OF THE FCU CONNECTOR ROD - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
21-AUG-2008		MOS HRS/MSC A/R ENC		21-DEC-2012 3612:25 4722			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14398 R3	NO. 1 ENGINE - FIRST-STAGE PLANETARY GEAR SYSTEM - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
14-JUL-2011		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14407 R3	NO. 1 ENGINE - REPLACEMENT OF THE OIL PRESSURE TUBE OF THE NO. 3 & 4 BEARING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
30-OCT-2009		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14408 R2	NO. 1 ENGINE - TURBOPROP ENGINE CT ROTOR AIR-SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
14-MAY-2008		MOS		21-DEC-2012			
		HRS/MSC A/R		3612:25			
		ENC		4722			
SB PT6A-72-14411 R2	NO. 1 ENGINE - REPLACEMENT OF BOLT OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-AUG-2008		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14416 R1	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
10-SEP-2008		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14441	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF PY AND P3 INSULATED AIR PRESSURE TUBES, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-MAY-2010		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14447	NO. 1 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
26-NOV-2010		MOS		28-NOV-2011			
		HRS/MSC -		3319:59			
		ENC		4306			
SB PT6A-72-14450	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	
08-JUL-2011		MOS			7200 M		
		HRS/MSC -					
		ENC					
SB PT6A-72-14451	NO. 1 ENGINE - REPLACEMENT OF NO.2 BEARING OIL PACKING, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
01-JUN-2011		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14452 R1	NO. 1 ENGINE - ELECTRICAL OIL LEVEL FILLER CAP AND INDICATOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
02-AUG-2011		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14485	NO. 1 ENGINE - REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS, SERVICE BULLETIN						COMPLIED WITH
07-MAY-2014		MOS		08-JUL-2014			
		HRS/MSC -		3816:24			
		ENC		5018			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14495 R1	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
09-DEC-2014		MOS		24-JUN-2015			
		HRS/MSC -		4082:48			
		ENC		5485			
SB PT6A-72-14495 R2	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A DUE TO ENGINE TYPE.
09-DEC-2014		MOS		12-OCT-2015			
		HRS/MSC -		4148:36			
		ENC		5567			
SB PT6A-72-14495 R3	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV. 1 PERFORMED AT 24/06/2015 (SEE CRS LPR SOTWO/03/MXH/2015)
		MOS		18-DEC-2015			
		HRS/MSC -		4148:36			
		ENC		5567			
SB PT6A-72-14496	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
19-DEC-2014		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14496 R1	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
11-MAR-2015		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14496 R2	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
13-APR-2015		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14496 R3	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14498	NO. 1 ENGINE - INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS		31-MAR-2015			
		HRS/MSC -		4057:13			
		ENC		5444			
SB A PT6A-72-14498 PART	NO. 1 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIR (PER OHM IN A P&WC SERVICE CENTER OR P&WC DOF)						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS		31-MAR-2015			
		HRS/MSC -		4057:13			
		ENC		5444			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14498 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIRED (PER OHM DATED MAR 24/2014 IN ANOTHER FACILITY (NOT P&WC SERVICE CENTERS OR P&WC DOFS))						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS HRS/MSC - ENC		31-MAR-2015 4057:13 5444			
SB PT6A-72-14499	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
01-MAY-2015		MOS HRS/MSC - ENC		06-MAY-2015 4082:48 5485			
SB PT6A-72-14499 PART A	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
01-MAY-2015		MOS HRS/MSC - ENC		06-MAY-2015 4082:48 5485			
SB PT6A-72-14499 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
01-MAY-2015		MOS HRS/MSC - ENC		06-MAY-2015 4082:48 5485			
SB PT6A-72-14499 R1	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
19-AUG-2015		MOS HRS/MSC - ENC		26-AUG-2015 4148:36 5566			
SB PT6A-72-14499 R1 PART A	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
19-AUG-2015		MOS HRS/MSC - ENC		26-AUG-2015 4148:36 5566			
SB PT6A-72-14499 R1 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
19-AUG-2015		MOS HRS/MSC - ENC		26-AUG-2015 4148:36 5566			
SB PT6A-72-14509	NO. 1 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N.
31-AUG-2015		MOS HRS/MSC - ENC		03-SEP-2015 4148:36 5566			
SB PT6A-72-14509 R3	NO. 1 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						COMPLIED WITH
19-OCT-2016		MOS HRS/MSC - ENC		05-JUN-2018 4559:47 6137			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 15-Sep-2020

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14603 R18	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-SEP-2012		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14603 R19	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
26-SEP-2012		MOS HRS/MSC - ENC		29-MAY-2013			
SPB 60 R1	NO. 1 ENGINE - TUBE FLANGED OIL FILLER OPTIONS - INTRDUCTION OF, SPARE PART BULLETIN						COMPLIED WITH - SPARE PART SB
		MOS HRS/MSC A/R ENC		06-AUG-2013 3692:35			
SPB 70 R1	NO. 1 ENGINE - OIL FILLER TUBE - REPLACEMENT OF, SPARE PART BULLETIN						COMPLIED WITH - SPARE PART SB
		MOS HRS/MSC A/R ENC		06-AUG-2013 3692:35			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 2 - SB - PCE-RK0103/3037000</b>							
ASB PT6A-72-A14410	NO. 2 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
06-SEP-2007		MOS		20-SEP-2007			
		HRS/MSC -					
		ENC					
ASB PT6A-72-A14410 R1	NO. 2 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO PART NUMBER
20-SEP-2007		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
ASB PT6A-72-A14410 R2	NO. 2 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN						NOT APPLICABLE
18-FEB-2014		MOS		07-MAR-2014			
		HRS/MSC -		4006:42			
		ENC		5218			
SB PT6A-72-14001 R16	NO. 2 ENGINE - TURBOPROP ENGINE APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH - INFORMATION ONLY REGARDING THE APPROVED USING OILS.
20-MAR-2015		MOS		11-SEP-2015			
		HRS/MSC -		4319:02			
		ENC		5737			
SB PT6A-72-14002 R21	NO. 2 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
12-DEC-2011		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14002 R22	NO. 2 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
16-NOV-2012		MOS		27-NOV-2014			
		HRS/MSC -		4090:55			
		ENC		5396			
SB PT6A-72-14048 R3	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INNER AND OUTER COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14061 R2	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SECTION, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
23-JUN-1993		MOS		30-JAN-2004			
		HRS/MSC N/R (s)		0			
		ENC		0			
SB PT6A-72-14089 R1	NO. 2 ENGINE - INTRODUCTION OF IMPROVED HIGHER LOAD BEARING CAPACITY CONFIGURATION NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
12-MAR-2010		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14109 R1	NO. 2 ENGINE - TURBOPROP ENGINE COMPRESSOR ROTOR SHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
14-MAY-2008		MOS		23-DEC-2012			
		HRS/MSC A/R		3706:50			
		ENC		4821			



# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14142 R3	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE BLADE WITH FEATHER SEALS, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
17-SEP-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14144 R2	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE (CT) STATOR ASSEMBLY, CT SHROUD HOUSING, SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
01-APR-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14162 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO AFFECTED PROPELLER GOVERNOR P/NS ARE NOT INSTALLED ON ENGINES
09-APR-2018		MOS HRS/MSC - ENC		12-APR-2018			
SB PT6A-72-14269 R5	NO. 2 ENGINE - REPLACEMENT OF P3 AIR PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N
01-MAR-2015		MOS HRS/MSC - ENC		23-MAR-2015 4213:24 5598			
SB PT6A-72-14270 R1	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO POST SB 14067
13-MAY-1998		MOS HRS/MSC N/R (s) ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14274 R1	NO. 2 ENGINE - PT6A-66 MINIMUM STANDARD CONFIGURATION REQUIREMENT TO UPGRADE HOT SECTION COMPONENTS, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
03-NOV-2009		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14275 R2	NO. 2 ENGINE - REPLACEMENT OF OIL FILLER CAP AND LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
13-JUN-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14301 R2	NO. 2 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART NUMBER
03-FEB-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14308 R3	NO. 2 ENGINE - REPLACEMENT OF REDUCTION GEARBOX SCAVENGE LINE, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
04-OCT-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14317 R3	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF INNER AND OUTER LINER, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - PREVIOUSLY
14-DEC-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

AIRCRAFT

All Bulletins with Compliance or Due  
Report Date: 15-Sep-2020

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14329 R4	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
30-APR-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14346 R2	NO. 2 ENGINE - INTRODUCTION OF NO.2 BEARING OIL NOZZLE WITH RETAINING RING, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
06-MAY-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14357 R4	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS HRS/MSC - ENC		27-NOV-2014 4090:55 5396			
SB PT6A-72-14365 R1	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - RK0103 HAS INSTALLED SB 14364. WHEN SB 14364 HAS BEEN INSTALLED SB 14365 IS N/A.
08-JAN-2013		MOS HRS/MSC - ENC		03-MAR-2013 3706:50 4821			
SB PT6A-72-14376	NO. 2 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - THIS SB IS N/A FOR ENGINE PCE-RK0103 DUE TO PARKER FUEL PUMP INSTALLED ON THE ENGINE (NOT SUNSTRAND AS SB REFER)
17-AUG-2012		MOS HRS/MSC - ENC		03-MAR-2013 3706:50 4821			
SB PT6A-72-14376 R1	NO. 2 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
22-OCT-2013		MOS HRS/MSC - ENC		14-JUL-2014 4085:35 5335			
SB PT6A-72-14377 R01	NO. 2 ENGINE - REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, SERVICE BULLETIN						DEFERRED
26-AUG-2015		MOS HRS/MSC - ENC		27-AUG-2015 4319:02 5737			
SB PT6A-72-14383	NO. 2 ENGINE - REPAIR OF FILLER CAP AND ELECTRIC OIL LEVEL DIPSTICK, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - PREVIOUSLY
26-FEB-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14395 R3	NO. 2 ENGINE - BOLTS AND NUTS OF THE FCU CONNECTOR ROD - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
21-AUG-2008		MOS HRS/MSC A/R ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14398 R3	NO. 2 ENGINE - FIRST-STAGE PLANETARY GEAR SYSTEM - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
14-JUL-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks \*-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14407 R3	NO. 2 ENGINE - REPLACEMENT OF THE OIL PRESSURE TUBE OF THE NO. 3 & 4 BEARING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
30-OCT-2009		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14408	NO. 2 ENGINE - REPLACEMENT OF CT ROTOR AIR-SEAL, SERVICE BULLETIN						COMPLIED WITH
13-NOV-2007		MOS HRS/MSC A/R ENC		02-SEP-2009 2396:59 3092			
SB PT6A-72-14408 R2	NO. 2 ENGINE - TURBOPROP ENGINE CT ROTOR AIR-SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PREVIOUSLY
14-MAY-2008		MOS HRS/MSC A/R ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14411 R2	NO. 2 ENGINE - REPLACEMENT OF BOLT OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-AUG-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14416 R1	NO. 2 ENGINE - REPLACEMENT OF POWER TURBINE AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
10-SEP-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14428 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES, SERVICE BULLETIN					CATEGORY 7	
20-APR-2012		MOS HRS/MSC - ENC			6000 M		
SB PT6A-72-14441	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF PY AND P3 INSULATED AIR PRESSURE TUBES, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-MAY-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14447	NO. 2 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
26-NOV-2010		MOS HRS/MSC - ENC		25-NOV-2011 3319:59 4306			
SB PT6A-72-14450	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	DECLINED
08-JUL-2011		MOS HRS/MSC - ENC		15-APR-2013 3748:05 4881			
SB PT6A-72-14451	NO. 2 ENGINE - REPLACEMENT OF NO.2 BEARING OIL PACKING, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
01-JUN-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14452 R1	NO. 2 ENGINE - ELECTRICAL OIL LEVEL FILLER CAP AND INDICATOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
02-AUG-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

AIRCRAFT

All Bulletins with Compliance or Due  
Report Date: 15-Sep-2020

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14485	NO. 2 ENGINE - REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS, SERVICE BULLETIN						COMPLIED WITH
07-MAY-2014		MOS HRS/MSC - ENC		27-NOV-2014 4090:55 5396			
SB PT6A-72-14495 R1	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
09-DEC-2014		MOS HRS/MSC - ENC		24-JUN-2015 4253:14 5658			
SB PT6A-72-14495 R2	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A DUE TO ENGINE TYPE.
09-DEC-2014		MOS HRS/MSC - ENC		12-OCT-2015 4319:06 5738			
SB PT6A-72-14495 R3	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV. 1 PERFORMED AT 24/06/2015 (SEE CRS LPR SOTWO/03/MXH/2015)
		MOS HRS/MSC - ENC		18-DEC-2015 4319:06 5738			
SB PT6A-72-14496	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
19-DEC-2014		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14496 R1	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
11-MAR-2015		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14496 R2	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
13-APR-2015		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14496 R3	NO. 2 ENGINE - INSPECTION / REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14498	NO. 2 ENGINE - INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS HRS/MSC - ENC		31-MAR-2015 4227:39 5618			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB A	PT6A-72-14498 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIR (PER OHM IN A P&WC SERVICE CENTER OR P&WC DOF)						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
	20-MAR-2015	MOS HRS/MSC - ENC		31-MAR-2015 4227:39 5618			
SB B	PT6A-72-14498 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIRED (PER OHM DATED MAR 24/2014 IN ANOTHER FACILITY (NOT P&WC SERVICE CENTERS OR P&WC DOFS))						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
	20-MAR-2015	MOS HRS/MSC - ENC		31-MAR-2015 4227:39 5618			
SB	PT6A-72-14499 NO. 2 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
	01-MAY-2015	MOS HRS/MSC - ENC		06-MAY-2015 4253:14 5658			
SB A	PT6A-72-14499 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
	01-MAY-2015	MOS HRS/MSC - ENC		06-MAY-2015 4253:14 5658			
SB B	PT6A-72-14499 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
	01-MAY-2015	MOS HRS/MSC - ENC		06-MAY-2015 4253:14 5658			
SB	PT6A-72-14499 R1 NO. 2 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
	19-AUG-2015	MOS HRS/MSC - ENC		26-AUG-2015 4319:02 5737			
SB PT6A-72-14499 R1 PART A	NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
	19-AUG-2015	MOS HRS/MSC - ENC		26-AUG-2015 4319:02 5737			
SB PT6A-72-14499 R1 PART B	NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
	19-AUG-2015	MOS HRS/MSC - ENC		26-AUG-2015 4319:02 5737			
SB	PT6A-72-14509 NO. 2 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N.
	31-AUG-2015	MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			

# Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5611:59HRS, 8577 AFL as of 13-Sep-2020

**AIRCRAFT**  
**All Bulletins with Compliance or Due**  
**Report Date: 15-Sep-2020**

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14509 R3	NO. 2 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						COMPLIED WITH
19-OCT-2016		MOS		05-JUN-2018			
		HRS/MSC	-	4729:58			
		ENC		6282			
SB PT6A-72-14603 R18	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-SEP-2012		MOS		23-DEC-2012			
		HRS/MSC	-	3706:50			
		ENC		4821			
SB PT6A-72-14603 R19	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - FOR ENGINES RK0103/4 AND RK0198/9 NO CHANGE IN THIS REV. ARE INCLUDE.
26-SEP-2012		MOS		03-MAR-2013			
		HRS/MSC	-	3706:50			
		ENC		4821			
SB PT6A-72-14603 R22	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
12-DEC-2013		MOS		27-NOV-2014			
		HRS/MSC	-	4090:55			
		ENC		5396			
SPB 60 R1	NO. 2 ENGINE - TUBE FLANGED OIL FILLER OPTIONS - INTRDUCTION OF, SPARE PART BULLETIN						DEFERRED
		MOS		15-APR-2013			
		HRS/MSC	A/R	3748:05			
		ENC		4881			
SPB 70 R1	NO. 2 ENGINE - OIL FILLER TUBE - REPLACEMENT OF, SPARE PART BULLETIN						DEFERRED
		MOS		15-APR-2013			
		HRS/MSC	A/R	3748:05			
		ENC		4881			