

OWNER:	POLISH AIR MEDICAL RESCUE / LOTNICZE POGOTOWIE RATUNKOWE	OPERATOR:	POLISH AIR MEDICAL RESCUE / LOTNICZE POGOTOWIE RATUNKOWE
ADDRESS:	KSIEZYCOWA 5 WARSZAWA 01-934	ADDRESS:	KSIEZYCOWA 5 WARSZAWA 01-934
PHONE:	+48 (22) 22-99-931	PHONE:	+48 (22) 22-99-931
FAX:		FAX:	
ANALYST:	MAXIME MOREAU	+33-1.55.93.47.74 (DIRECT)	
EMAIL:	MAXIME.MOREAU@CAMPSYSTEMS.EU	+33 (0) 1.55.93.45.80 (OFFICE)	
		WWW.CAMPSYSTEMS.COM	
PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.			

Filter Criteria: ATA From: 70 - To: 79; Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

AIRCRAFT SERIAL/REGNO: 1079/SP-MXH **MODEL:** PIAGGIO P180 AVANTI EASA.A.059 **MANUFACTURER:** PIAGGIO AEROSPACE

DATES	LAST ACTUALS	CURRENT ACTUAL
CERTIFICATION DATE: 22-APR-2004	5736 A/C HRS as of 11-FEB-2021	A/C HRS as of ____/____/____
	8761 AFL as of 28-JAN-2021	AFL as of ____/____/____

ENGINE NO. 1 SERIAL/PART: PCE-RK0104/3037000 **MODEL:** PT6A-66 **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 21-JUL-2014	LAST ACTUALS	CURRENT ACTUAL
3816:24 ENG. HRS 4076:57 A/C HRS	5473:26 ENG. HRS as of 11-FEB-2021	ENG. HRS as of ____/____/____
5018 ENC	7409 ENC as of 28-JAN-2021	ENC as of ____/____/____

ENGINE NO. 2 SERIAL/PART: PCE-RK0103/3037000 **MODEL:** PT6A-66 **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 13-JAN-2015	LAST ACTUALS	CURRENT ACTUAL
4090:59 ENG. HRS 4183:03 A/C HRS	5643:56 ENG. HRS as of 11-FEB-2021	ENG. HRS as of ____/____/____
5396 ENC	7526 ENC as of 28-JAN-2021	ENC as of ____/____/____

PROPELLER NO SERIAL/PART: KU85-E/HC-E5N-3A **MODEL:** HC-E5N-3A **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 03-JUN-2019	LAST ACTUALS	CURRENT ACTUAL
5597:18 PROP HRS 5156:54 A/C HRS	6244:17 PROP HRS as of 11-FEB-2021	PROP HRS as of ____/____/____

PROPELLER NO SERIAL/PART: HF217-E/HC-E5N-3AL **MODEL:** HC-E5N-3AL **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 03-JUN-2019	LAST ACTUALS	CURRENT ACTUAL
5549:53 PROP HRS 5156:54 A/C HRS	6196:40 PROP HRS as of 11-FEB-2021	PROP HRS as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - AD - 1079/SP-MXH							
EASA 2010-0123	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT					SUPERSEDED	COMPLIED WITH
06-JUL-2010		MOS HRS/MSC - AFL		29-NOV-2011 3319:59 5183			
EASA 2010-0123 R01	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - CANCELLED DUE TO DIPSTICK HAS BEEN CHANGED FOR NEW ONE WHERE THIS INSPECTION IS N/A. IAW AD NO MORE ACTION IS REQUIRED.
		MOS HRS/MSC - AFL		09-AUG-2013 3836:53 5941			
EASA 2010-0125 PART (1)	OIL - OIL COOLING SYSTEM HOSE - INSPECTION						COMPLIED WITH - CLOSED
		MOS HRS/MSC - AFL		05-JUN-2018 4823:15 7386			
ENAC 1993-034	HEAT EXCHANGER EXHAUST GAS/HEATING AIR FOR COCKPIT AND PASSENGER CABIN.						NOT APPLICABLE - BY EFFECTIVITY
15-MAR-1993		MOS HRS/MSC - AFL		22-APR-2004 0 0			
ENAC 1995-087	ENGINE POWER AND PROPELLER CONTROLS - WATER PROTECTION						NOT APPLICABLE
		MOS HRS/MSC - AFL		22-APR-2004 0 0			
ENAC 2002-335 PART (A)	OIL COOLING SYSTEM - INSPECTION CHECK.					SUPERSEDED	COMPLIED WITH
		MOS HRS/MSC - AFL		30-AUG-2016 4685:51 7191			
ENAC 2002-335 PART (B)	OIL COOLING SYSTEM - INSPECTION CHECK.					SUPERSEDED	COMPLIED WITH
		MOS HRS/MSC - (s) AFL		15-NOV-2008 1995:52 2995			
ENAC 2010-215	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT -					MANDATORY	COMPLIED WITH
23-JUN-2010		MOS HRS/MSC - AFL		03-JAN-2011 3000:47 4719			
ENAC 2010-220 PART (1)	OIL - OIL COOLING SYSTEM HOSE - INSPECTION					MANDATORY	COMPLIED WITH
		MOS HRS/MSC - AFL		05-JUN-2018 4823:15 7386			
ENAC 2011-353	OIL - ENGINE OIL DIPSTICK - INSPECTION / REPLACEMENT					MANDATORY	NOT APPLICABLE - CANCELLED DUE TO DIPSTICK HAS BEEN CHANGED FOR NEW ONE WHERE THIS INSPECTION IS N/A. IAW AD NO MORE ACTION IS REQUIRED.
		MOS HRS/MSC - AFL		09-AUG-2013 3836:53 5941			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
AIRFRAME - SB - 1079/SP-MXH							
SB 80-0022	MODIFIED EXHAUST STACKS - INSTALLATION, SERVICE BULLETIN					RECOMMENDED	NOT APPLICABLE
		MOS		22-APR-2004			
06-JUL-1992		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0027	MAGNETIC CHIP DETECTOR INDICATION - INSTALLATION, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		22-APR-2004			
12-MAY-1992		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0040	POWER LEVER "GO-AROUND" AND "GEAR MUTE" SWITCHES - CHANGE OF THEIR MUTUAL POSITIONS, SERVICE BULLETIN					OPTIONAL	NOT APPLICABLE
		MOS		22-APR-2004			
20-MAY-1993		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0066	POWER AND PROPELLER CONTROLS - WATER PROTECTION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		22-APR-2004			
12-DEC-1994		HRS/MSC	-	0			
		AFL		0			
SB 80-0080	PROPELLER LOW PITCH STOP SWITCH - MODIFICATION, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE
		MOS		22-APR-2004			
03-JUL-1995		HRS/MSC	-	0			
		AFL		0			
SB 80-0092	PLENUM ZONE MODIFICATION IN CASE OF INSTALLATION OF ENGINES EQUIPPED WITH IMPROVED BLEED OFF VALVES, SERVICE BULLETIN					OPTIONAL	COMPLIED WITH
		MOS		22-APR-2004			
14-APR-1997		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0129	CENTER AND REAR FIREWALLS MODIFICATION FOLLOWING ENGINE MODIFICATION AS PER LAST ISSUE OF PRATT & WHITNEY CANADA S.B. NO.14308, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		22-APR-2004			
22-SEP-2000		HRS/MSC	N/R (s)	0			
		AFL		0			
SB 80-0145	P/N 80-336013-403 EXHAUST STACKS - INSPECTION/REPAIR AS NECESSARY, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS		30-JAN-2008			
17-JUN-2005		HRS/MSC	-	1555:36			
		AFL		2308			
SB 80-0145 REV.1	P/N 80-336013-403 EXHAUST STACKS - INSPECTION/REPAIR AS NECESSARY, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH - ALREADY CW IAW PREVIOUS REVISION
		MOS		12-DEC-2011			
02-DEC-2011		HRS/MSC	-	3340:19			
		AFL		5212			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 80-0145 REV.2	P/N 80-336013-403 EXHAUST STACKS - INSPECTION / REPAIR / REPLACEMENT AS NECESSARY, SERVICE BULLETIN					SUPERSEDED	NOT APPLICABLE - N/A DUE TO COMPLETED REV. 0 OF THIS SB. SEE SCE 1178/1124 FROM 30.01.2008. NO ACTION REQUIRED FOR OPERATORS WHO PERFORMED PREVIOUS ISSUE OF THIS SB.
29-MAR-2013		MOS		17-APR-2013			
		HRS/MSC -		3805:01			
		AFL		5891			
SB 80-0145 REV.3	P/N 80-336013-403 EXHAUST STACKS - INSPECTION / REPAIR / REPLACEMENT AS NECESSARY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		05-JUN-2018			
		HRS/MSC -		4823:15			
		AFL		7386			
SB A 80-0175 REV 01 PART	OIL COOLING SYSTEM TUBING INSTALLATION CLEARANCE FROM THE ENGINE MOUNTED OIL-TO-FUEL HEATER - INSPECTION CHECK, SERVICE BULLETIN					MANDATORY	COMPLIED WITH - CLOSED
		MOS		05-JUN-2018			
		HRS/MSC -		4823:15			
		AFL		7386			
SB B 80-0175 REV 01 PART	OIL COOLING SYSTEM TUBING INSTALLATION CLEARANCE FROM THE ENGINE MOUNTED OIL-TO-FUEL HEATER - INSPECTION CHECK, SERVICE BULLETIN					MANDATORY	COMPLIED WITH
		MOS		05-JUN-2018			
		HRS/MSC	A/R (s)	4823:15			
		AFL		7386			
SB 80-0194	CHIP DETECTOR MONITORING SYSTEM - INSTALLATION, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - AT MANUFACTURE
		MOS		26-MAY-2004			
		HRS/MSC	A/R				
		AFL					
SB 80-0287	ENGINE OIL LEVEL CHECK, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS		25-MAR-2010			
		HRS/MSC -		2663:54			
		AFL		4202			
SB 80-0287 REV.1	ENGINE OIL LEVEL CHECK, SERVICE BULLETIN					SUPERSEDED	COMPLIED WITH
		MOS		22-NOV-2011			
		HRS/MSC -		3300:14			
		AFL		5156			
SB 80-0287 REV.2	ENGINE OIL LEVEL CHECK, SERVICE BULLETIN					MANDATORY	NOT APPLICABLE - CANCELLED DUE TO DIPSTICK HAS BEEN CHANGED FOR NEW ONE WHERE THIS INSPECTION IS N/A. IAW AD NO MORE ACTION IS REQUIRED.
		MOS		09-AUG-2013			
		HRS/MSC -		3836:53			
		AFL		5941			
SB 80-0315	THROTTLE QUADRANT -MICROSWITCHES LEVERS IMPROVEMENT, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
		MOS		03-JUN-2011			
		HRS/MSC -		3026:56			
		AFL		4753			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB 80-0421	REPLACEMENT OF ENGINE OIL HOSE ASSY (OIL COOLER TO ENGINE), SERVICE BULLETIN	MOS				RECOMMENDED	NOT APPLICABLE - DUE TO MSN
16-NOV-2017		HRS/MSC -					
		AFL					
SB 80-0421 PART A	ACCOMPLISH REPLACEMENT OF ENGINE OIL HOSE ASSY (OIL COOLER TO ENGINE), SERVICE BULLETIN REMOVAL OF UPPER AND LOWER NACELLES; OIL COOLING SYSTEM INSPECTION; INSTALLATION OF UPPER AND LOWER NACELLES	MOS				RECOMMENDED	NOT APPLICABLE - DUE TO MSN
16-NOV-2017		HRS/MSC -					
		AFL					
SB 80-0421 PART B	ACCOMPLISH REPLACEMENT OF ENGINE OIL HOSE ASSY (OIL COOLER TO ENGINE), SERVICE BULLETIN INSTALLATION OF THE NEW HOSE ASSY P/N 80-337283-001 AND FITTING P/N 80-337290-001 (FOR LH ENGINE ONLY) (FOLLOWING INSPECTION FINDINGS IAW PART A OF THIS SB)	MOS				RECOMMENDED	NOT APPLICABLE - DUE TO MSN
16-NOV-2017		HRS/MSC - (s)					
		AFL					
SB 80-0440	INSPECTION OF PROPELLER CONTROL CAM ASSEMBLY, SERVICE BULLETIN	MOS		12-OCT-2015		SUPERSEDED	NOT APPLICABLE - N/A DUE TO MSN
30-OCT-2015		HRS/MSC -		4411:10			
		AFL		6783			
SB 80-0440 PART A	VISUAL INSPECTION INSPECTION OF PROPELLER CONTROL CAM ASSEMBLY, SERVICE BULLETIN OF PROPELLER CONTROL CAM ASSEMBLY	MOS		12-OCT-2015		SUPERSEDED	NOT APPLICABLE - N/A DUE TO MSN
30-OCT-2015		HRS/MSC -		4411:10			
		AFL		6783			
SB 80-0440 PART B	REWORK INSPECTION OF PROPELLER CONTROL CAM ASSEMBLY, SERVICE BULLETIN OF THE WASHER P/N NAS1149C0316R	MOS		12-OCT-2015		SUPERSEDED	NOT APPLICABLE
30-OCT-2015		HRS/MSC -		4411:10			
		AFL		6783			
SB 80-0442	INSPECTION/REPAIR OF P180 LH WING - INTERFERENCE BETWEEN HOSE P/N 3112402-01 OR 3108703-01 AND REAR SPAR FIREWALL P/N 80-336061-007, SERVICE BULLETIN	MOS		05-JUN-2018		RECOMMENDED	COMPLIED WITH
18-DEC-2015		HRS/MSC -		4823:15			
		AFL		7386			
SB 80-0461	P180 ENGINE MOUNTS AND ENGINE MOUNTS ELECTRICAL BONDING CONNECTIONS - CHECK, SERVICE BULLETIN	MOS		22-APR-2004		MANDATORY	
25-JAN-2018		HRS/MSC -					
		AFL					
SB 80-0480	INSPECTION OF PROPELLER REVERSING LEVER AND GUIDE PIN INSTALLATION, SERVICE BULLETIN	MOS		10-APR-2020		MANDATORY	NOT APPLICABLE - DUE TO ENGINES, PROPELLERS, PROPELLER GOVERNORS AND PROPELLER BETA RINGS HAS NOT BEEN REPLACED IN THE LAST 150 FH
08-APR-2020		HRS/MSC -					
		AFL					

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - AD - PCE-RK0104/3037000							
FAA 2012-09-10	NO. 1 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLER REDUCTION GEARBOX ASSEMBLY					MANDATORY	NOT APPLICABLE - N/A DUE TO DIFFERENT P/N OF PARTS INSTALLED ON 1079, LISTED IN SUBJECT AD.
		MOS			11-MAY-2012		
		HRS/MS	-		3524:37		
		AFL					
		ENC			4581		

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - AD - PCE-RK0103/3037000							
FAA 2012-09-10	NO. 2 ENGINE - REMOVE FROM SERVICE PMA REPLACEMENT TAATI FIRST STAGE SUN GEAR AND THE PLANET GEARS FROM THE PROPELLER REDUCTION GEARBOX ASSEMBLY					MANDATORY	COMPLIED WITH
		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
LBA D-2012-210	NO. 2 ENGINE - TURBINE ENGINE -TIMKEN ALCOR AEROSPACE TECHNOLOGIES, INC. FIRST STAGE SUN GEARS AND PLANET GEARS - REMOVAL FROM SERVICE					MANDATORY	COMPLIED WITH
		MOS		23-DEC-2012			
		HRS/MSC - (s)		3706:50			
		ENC		4821			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 1 - SB - PCE-RK0104/3037000							
ASB PT6A-72-A14410	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
06-SEP-2007		MOS HRS/MSC - ENC		20-SEP-2007			
ASB PT6A-72-A14410 R1	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
20-SEP-2007		MOS HRS/MSC - ENC		20-SEP-2007			
ASB PT6A-72-A14410 R2	NO. 1 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN						NOT APPLICABLE
18-FEB-2014		MOS HRS/MSC - ENC		07-MAR-2014 3854:38 5015			
SB PT6A-72-14001 R16	NO. 1 ENGINE - TURBOPROP ENGINE APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH - INFORMATION ONLY REGARDING THE APPROVED USING OILS.
20-MAR-2015		MOS HRS/MSC - ENC		11-SEP-2015 4148:36 5566			
SB PT6A-72-14002 R21	NO. 1 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
12-DEC-2011		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14002 R22	NO. 1 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
16-NOV-2012		MOS HRS/MSC - ENC		29-MAY-2013			
SB PT6A-72-14015 R2	NO. 1 ENGINE - REPLACEMENT OF NEW COMPRESSOR TURBINE BOLT, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N DOESN'T MEET REQUIREMENTS OF SB
16-DEC-2014		MOS HRS/MSC - ENC		12-DEC-2014 5222			
SB PT6A-72-14048 R3	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INNER AND OUTER COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ESN
		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14061 R2	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SECTION, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
23-JUN-1993		MOS HRS/MSC N/R (s) ENC		03-FEB-2004 0 0			
SB PT6A-72-14089 R1	NO. 1 ENGINE - INTRODUCTION OF IMPROVED HIGHER LOAD BEARING CAPACITY CONFIGURATION NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - DUE TO ESN
12-MAR-2010		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14109 R1	NO. 1 ENGINE - TURBOPROP ENGINE COMPRESSOR ROTOR SHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - DUE TO ESN
14-MAY-2008		MOS HRS/MSC A/R ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14142 R3	NO. 1 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE BLADE WITH FEATHER SEALS, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ESN
17-SEP-2008		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14144 R2	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE (CT) STATOR ASSEMBLY, CT SHROUD HOUSING, SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ESN
01-APR-2008		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14162 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO AFFECTED PROPELLER GOVERNOR P/NS ARE NOT INSTALLED ON ENGINES
09-APR-2018		MOS HRS/MSC - ENC		12-APR-2018			
SB PT6A-72-14269 R5	NO. 1 ENGINE - REPLACEMENT OF P3 AIR PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N
01-MAR-2015		MOS HRS/MSC - ENC		23-MAR-2015 4042:58 5423			
SB PT6A-72-14270 R1	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO POST SB 14067
13-MAY-1998		MOS HRS/MSC N/R (s) ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14274 R1	NO. 1 ENGINE - PT6A-66 MINIMUM STANDARD CONFIGURATION REQUIREMENT TO UPGRADE HOT SECTION COMPONENTS, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
03-NOV-2009		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14275 R2	NO. 1 ENGINE - REPLACEMENT OF OIL FILLER CAP AND LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
13-JUN-2011		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14301 R2	NO. 1 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART NUMBER
03-FEB-2010		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14308 R3	NO. 1 ENGINE - REPLACEMENT OF REDUCTION GEARBOX SCAVENGE LINE, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
04-OCT-2011		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14317 R3	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF INNER AND OUTER LINER, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART SN AND ESN
14-DEC-2010		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14329 R4	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PREVIOUSLY EMBODIED
30-APR-2010		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14346 R2	NO. 1 ENGINE - INTRODUCTION OF NO.2 BEARING OIL NOZZLE WITH RETAINING RING, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART ESN
06-MAY-2011		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14357 R4	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS HRS/MSC - ENC		08-JUL-2014 3816:24 5018			
SB PT6A-72-14365 R1	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - RK0104 HAS INSTALLED SB 14364. WHEN SB 14364 HAS BEEN INSTALLED, SB 14365 IS N/A
08-JAN-2013		MOS HRS/MSC - ENC		03-MAR-2013 3660:46			
SB PT6A-72-14376	NO. 1 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A - THIS SB IS N/A FOR ENGINE PCE-RK0104 DUE TO PARKER FUEL PUMP INSTALLED ON THE ENGINE (NOT SUNSTAND AS SB REFER)
17-AUG-2012		MOS HRS/MSC - ENC		03-MAR-2013 3660:46			
SB PT6A-72-14376 R1	NO. 1 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
22-OCT-2013		MOS HRS/MSC - ENC		16-OCT-2014 5208			
SB PT6A-72-14377 R01	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, SERVICE BULLETIN						DEFERRED
26-AUG-2015		MOS HRS/MSC - ENC		27-AUG-2015 4148:36 5566			
SB PT6A-72-14383	NO. 1 ENGINE - REPAIR OF FILLER CAP AND ELECTRIC OIL LEVEL DIPSTICK, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
26-FEB-2010		MOS HRS/MSC - ENC		10-APR-2010 2663:54 3498			
SB PT6A-72-14395 R3	NO. 1 ENGINE - BOLTS AND NUTS OF THE FCU CONNECTOR ROD - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
21-AUG-2008		MOS HRS/MSC A/R ENC		21-DEC-2012 3612:25 4722			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14398 R3	NO. 1 ENGINE - FIRST-STAGE PLANETARY GEAR SYSTEM - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
14-JUL-2011		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14407 R3	NO. 1 ENGINE - REPLACEMENT OF THE OIL PRESSURE TUBE OF THE NO. 3 & 4 BEARING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
30-OCT-2009		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14408 R2	NO. 1 ENGINE - TURBOPROP ENGINE CT ROTOR AIR-SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
14-MAY-2008		MOS		21-DEC-2012			
		HRS/MSC A/R		3612:25			
		ENC		4722			
SB PT6A-72-14411 R2	NO. 1 ENGINE - REPLACEMENT OF BOLT OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-AUG-2008		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14416 R1	NO. 1 ENGINE - REPLACEMENT OF POWER TURBINE AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
10-SEP-2008		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14441	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF PY AND P3 INSULATED AIR PRESSURE TUBES, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-MAY-2010		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14447	NO. 1 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
26-NOV-2010		MOS		28-NOV-2011			
		HRS/MSC -		3319:59			
		ENC		4306			
SB PT6A-72-14450	NO. 1 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	
08-JUL-2011		MOS			7200 M		
		HRS/MSC -					
		ENC					
SB PT6A-72-14451	NO. 1 ENGINE - REPLACEMENT OF NO.2 BEARING OIL PACKING, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
01-JUN-2011		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14452 R1	NO. 1 ENGINE - ELECTRICAL OIL LEVEL FILLER CAP AND INDICATOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
02-AUG-2011		MOS		21-DEC-2012			
		HRS/MSC -		3612:25			
		ENC		4722			
SB PT6A-72-14485	NO. 1 ENGINE - REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS, SERVICE BULLETIN						COMPLIED WITH
07-MAY-2014		MOS		08-JUL-2014			
		HRS/MSC -		3816:24			
		ENC		5018			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14495 R1	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
09-DEC-2014		MOS		24-JUN-2015			
		HRS/MSC -		4082:48			
		ENC		5485			
SB PT6A-72-14495 R2	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A DUE TO ENGINE TYPE.
09-DEC-2014		MOS		12-OCT-2015			
		HRS/MSC -		4148:36			
		ENC		5567			
SB PT6A-72-14495 R3	NO. 1 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV. 1 PERFORMED AT 24/06/2015 (SEE CRS LPR SOTWO/03/MXH/2015)
		MOS		18-DEC-2015			
		HRS/MSC -		4148:36			
		ENC		5567			
SB PT6A-72-14496	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
19-DEC-2014		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14496 R1	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
11-MAR-2015		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14496 R2	NO. 1 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
13-APR-2015		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14496 R3	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
		MOS		03-SEP-2015			
		HRS/MSC -		4148:36			
		ENC		5566			
SB PT6A-72-14498	NO. 1 ENGINE - INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS		31-MAR-2015			
		HRS/MSC -		4057:13			
		ENC		5444			
SB A PT6A-72-14498 PART	NO. 1 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIR (PER OHM IN A P&WC SERVICE CENTER OR P&WC DOF)						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS		31-MAR-2015			
		HRS/MSC -		4057:13			
		ENC		5444			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14498 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIRED (PER OHM DATED MAR 24/2014 IN ANOTHER FACILITY (NOT P&WC SERVICE CENTERS OR P&WC DOFS))						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS HRS/MSC - ENC		31-MAR-2015 4057:13 5444			
SB PT6A-72-14499	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
01-MAY-2015		MOS HRS/MSC - ENC		06-MAY-2015 4082:48 5485			
SB PT6A-72-14499 PART A	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
01-MAY-2015		MOS HRS/MSC - ENC		06-MAY-2015 4082:48 5485			
SB PT6A-72-14499 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
01-MAY-2015		MOS HRS/MSC - ENC		06-MAY-2015 4082:48 5485			
SB PT6A-72-14499 R1	NO. 1 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
19-AUG-2015		MOS HRS/MSC - ENC		26-AUG-2015 4148:36 5566			
SB PT6A-72-14499 R1 PART A	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
19-AUG-2015		MOS HRS/MSC - ENC		26-AUG-2015 4148:36 5566			
SB PT6A-72-14499 R1 PART B	NO. 1 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
19-AUG-2015		MOS HRS/MSC - ENC		26-AUG-2015 4148:36 5566			
SB PT6A-72-14509	NO. 1 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N.
31-AUG-2015		MOS HRS/MSC - ENC		03-SEP-2015 4148:36 5566			
SB PT6A-72-14509 R3	NO. 1 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						COMPLIED WITH
19-OCT-2016		MOS HRS/MSC - ENC		05-JUN-2018 4559:47 6137			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT

All Bulletins with Compliance or Due

Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14603 R18	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-SEP-2012		MOS HRS/MSC - ENC		21-DEC-2012 3612:25 4722			
SB PT6A-72-14603 R19	NO. 1 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
26-SEP-2012		MOS HRS/MSC - ENC		29-MAY-2013			
SPB 60 R1	NO. 1 ENGINE - TUBE FLANGED OIL FILLER OPTIONS - INTRDUCTION OF, SPARE PART BULLETIN						COMPLIED WITH - SPARE PART SB
		MOS HRS/MSC A/R ENC		06-AUG-2013 3692:35			
SPB 70 R1	NO. 1 ENGINE - OIL FILLER TUBE - REPLACEMENT OF, SPARE PART BULLETIN						COMPLIED WITH - SPARE PART SB
		MOS HRS/MSC A/R ENC		06-AUG-2013 3692:35			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
ENGINE NO. 2 - SB - PCE-RK0103/3037000							
ASB PT6A-72-A14410	NO. 2 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
06-SEP-2007		MOS		20-SEP-2007			
		HRS/MSC -					
		ENC					
ASB PT6A-72-A14410 R1	NO. 2 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO PART NUMBER
20-SEP-2007		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
ASB PT6A-72-A14410 R2	NO. 2 ENGINE - INSPECTION OF SPARK IGNITERS, ALERT SERVICE BULLETIN						NOT APPLICABLE
18-FEB-2014		MOS		07-MAR-2014			
		HRS/MSC -		4006:42			
		ENC		5218			
SB PT6A-72-14001 R16	NO. 2 ENGINE - TURBOPROP ENGINE APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS, SERVICE BULLETIN						COMPLIED WITH - INFORMATION ONLY REGARDING THE APPROVED USING OILS.
20-MAR-2015		MOS		11-SEP-2015			
		HRS/MSC -		4319:02			
		ENC		5737			
SB PT6A-72-14002 R21	NO. 2 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
12-DEC-2011		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14002 R22	NO. 2 ENGINE - TURBOPROP ENGINE ROTOR COMPONENTS - SERVICE LIFE, SERVICE BULLETIN						COMPLIED WITH
16-NOV-2012		MOS		27-NOV-2014			
		HRS/MSC -		4090:55			
		ENC		5396			
SB PT6A-72-14048 R3	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INNER AND OUTER COMBUSTION CHAMBER LINER ASSEMBLIES, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14061 R2	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE SECTION, SERVICE BULLETIN					CODE 8	COMPLIED WITH - AT MANUFACTURE
23-JUN-1993		MOS		30-JAN-2004			
		HRS/MSC N/R (s)		0			
		ENC		0			
SB PT6A-72-14089 R1	NO. 2 ENGINE - INTRODUCTION OF IMPROVED HIGHER LOAD BEARING CAPACITY CONFIGURATION NO. 1 BEARING, SERVICE BULLETIN					CATEGORY 8	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
12-MAR-2010		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14109 R1	NO. 2 ENGINE - TURBOPROP ENGINE COMPRESSOR ROTOR SHAFT ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 5	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
14-MAY-2008		MOS		23-DEC-2012			
		HRS/MSC A/R		3706:50			
		ENC		4821			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14142 R3	NO. 2 ENGINE - INTRODUCTION OF COMPRESSOR TURBINE BLADE WITH FEATHER SEALS, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
17-SEP-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14144 R2	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR TURBINE (CT) STATOR ASSEMBLY, CT SHROUD HOUSING, SMALL EXIT DUCT ASSEMBLY, SERVICE BULLETIN					CATEGORY 4	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
01-APR-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14162 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER GOVERNOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO AFFECTED PROPELLER GOVERNOR P/NS ARE NOT INSTALLED ON ENGINES
09-APR-2018		MOS HRS/MSC - ENC		12-APR-2018			
SB PT6A-72-14269 R5	NO. 2 ENGINE - REPLACEMENT OF P3 AIR PRESSURE TUBE ASSEMBLY, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N
01-MAR-2015		MOS HRS/MSC - ENC		23-MAR-2015 4213:24 5598			
SB PT6A-72-14270 R1	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL NOZZLES AND MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - DUE TO POST SB 14067
13-MAY-1998		MOS HRS/MSC N/R (s) ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14274 R1	NO. 2 ENGINE - PT6A-66 MINIMUM STANDARD CONFIGURATION REQUIREMENT TO UPGRADE HOT SECTION COMPONENTS, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
03-NOV-2009		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14275 R2	NO. 2 ENGINE - REPLACEMENT OF OIL FILLER CAP AND LEVEL INDICATOR, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
13-JUN-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14301 R2	NO. 2 ENGINE - REPLACEMENT OF FILLER CAP AND OIL GAGE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO PART NUMBER
03-FEB-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14308 R3	NO. 2 ENGINE - REPLACEMENT OF REDUCTION GEARBOX SCAVENGE LINE, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
04-OCT-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14317 R3	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF INNER AND OUTER LINER, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - PREVIOUSLY
14-DEC-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14329 R4	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER OUTER LINER, SERVICE BULLETIN					CATEGORY 7	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
30-APR-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14346 R2	NO. 2 ENGINE - INTRODUCTION OF NO.2 BEARING OIL NOZZLE WITH RETAINING RING, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - DUE TO ENGINE SERIAL NUMBER
06-MAY-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14357 R4	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE ASSEMBLY, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
		MOS HRS/MSC - ENC		27-NOV-2014 4090:55 5396			
SB PT6A-72-14365 R1	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - RK0103 HAS INSTALLED SB 14364. WHEN SB 14364 HAS BEEN INSTALLED SB 14365 IS N/A.
08-JAN-2013		MOS HRS/MSC - ENC		03-MAR-2013 3706:50 4821			
SB PT6A-72-14376	NO. 2 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - THIS SB IS N/A FOR ENGINE PCE-RK0103 DUE TO PARKER FUEL PUMP INSTALLED ON THE ENGINE (NOT SUNSTRAND AS SB REFER)
17-AUG-2012		MOS HRS/MSC - ENC		03-MAR-2013 3706:50 4821			
SB PT6A-72-14376 R1	NO. 2 ENGINE - INSPECTION OF TURBOPROP ENGINE WITH HAMILTON SUNSTRAND FUEL PUMP, COUPLING SHAFT SPLINE, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
22-OCT-2013		MOS HRS/MSC - ENC		14-JUL-2014 4085:35 5335			
SB PT6A-72-14377 R01	NO. 2 ENGINE - REPLACEMENT OF POWER TURBINE SHAFT HOUSING ASSEMBLY, SERVICE BULLETIN						DEFERRED
26-AUG-2015		MOS HRS/MSC - ENC		27-AUG-2015 4319:02 5737			
SB PT6A-72-14383	NO. 2 ENGINE - REPAIR OF FILLER CAP AND ELECTRIC OIL LEVEL DIPSTICK, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - PREVIOUSLY
26-FEB-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14395 R3	NO. 2 ENGINE - BOLTS AND NUTS OF THE FCU CONNECTOR ROD - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
21-AUG-2008		MOS HRS/MSC A/R ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14398 R3	NO. 2 ENGINE - FIRST-STAGE PLANETARY GEAR SYSTEM - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
14-JUL-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (ex)-Excluded Tasks *-Estimated Due (New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14407 R3	NO. 2 ENGINE - REPLACEMENT OF THE OIL PRESSURE TUBE OF THE NO. 3 & 4 BEARING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH
30-OCT-2009		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14408	NO. 2 ENGINE - REPLACEMENT OF CT ROTOR AIR-SEAL, SERVICE BULLETIN						COMPLIED WITH
13-NOV-2007		MOS HRS/MSC A/R ENC		02-SEP-2009 2396:59 3092			
SB PT6A-72-14408 R2	NO. 2 ENGINE - TURBOPROP ENGINE CT ROTOR AIR-SEAL - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - PREVIOUSLY
14-MAY-2008		MOS HRS/MSC A/R ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14411 R2	NO. 2 ENGINE - REPLACEMENT OF BOLT OF THE FCU CONNECTOR ROD, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-AUG-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14416 R1	NO. 2 ENGINE - REPLACEMENT OF POWER TURBINE AIR SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
10-SEP-2008		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14428 R1	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF PROPELLER-SHAFT OIL SEAL RETAINING-RING-HALVES, SERVICE BULLETIN					CATEGORY 7	
20-APR-2012		MOS HRS/MSC - ENC			6000 M		
SB PT6A-72-14441	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF PY AND P3 INSULATED AIR PRESSURE TUBES, SERVICE BULLETIN					CATEGORY 5	COMPLIED WITH
21-MAY-2010		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14447	NO. 2 ENGINE - INSPECTION OF GAS GENERATOR, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE
26-NOV-2010		MOS HRS/MSC - ENC		25-NOV-2011 3319:59 4306			
SB PT6A-72-14450	NO. 2 ENGINE - REPLACEMENT OF COMPRESSOR ROTOR AIR SEAL, SERVICE BULLETIN					CATEGORY 7	DECLINED
08-JUL-2011		MOS HRS/MSC - ENC		15-APR-2013 3748:05 4881			
SB PT6A-72-14451	NO. 2 ENGINE - REPLACEMENT OF NO.2 BEARING OIL PACKING, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
01-JUN-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			
SB PT6A-72-14452 R1	NO. 2 ENGINE - ELECTRICAL OIL LEVEL FILLER CAP AND INDICATOR - REPLACEMENT OF, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH
02-AUG-2011		MOS HRS/MSC - ENC		23-DEC-2012 3706:50 4821			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14485	NO. 2 ENGINE - REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS, SERVICE BULLETIN						COMPLIED WITH
07-MAY-2014		MOS HRS/MSC - ENC		27-NOV-2014 4090:55 5396			
SB PT6A-72-14495 R1	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH
09-DEC-2014		MOS HRS/MSC - ENC		24-JUN-2015 4253:14 5658			
SB PT6A-72-14495 R2	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN					CATEGORY 3	NOT APPLICABLE - N/A DUE TO ENGINE TYPE.
09-DEC-2014		MOS HRS/MSC - ENC		12-OCT-2015 4319:06 5738			
SB PT6A-72-14495 R3	NO. 2 ENGINE - INSPECTION OF FUEL NOZZLE TIPS, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV. 1 PERFORMED AT 24/06/2015 (SEE CRS LPR SOTWO/03/MXH/2015)
		MOS HRS/MSC - ENC		18-DEC-2015 4319:06 5738			
SB PT6A-72-14496	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
19-DEC-2014		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14496 R1	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN					CATEGORY 6	NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
11-MAR-2015		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14496 R2	NO. 2 ENGINE - INSPECTION/REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
13-APR-2015		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14496 R3	NO. 2 ENGINE - INSPECTION / REPLACEMENT OF FUEL PUMP, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ARGOTECH FUEL PUMP INSTALLED.
		MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			
SB PT6A-72-14498	NO. 2 ENGINE - INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
20-MAR-2015		MOS HRS/MSC - ENC		31-MAR-2015 4227:39 5618			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB A	PT6A-72-14498 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIR (PER OHM IN A P&WC SERVICE CENTER OR P&WC DOF)						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
	20-MAR-2015	MOS HRS/MSC - ENC		31-MAR-2015 4227:39 5618			
SB B	PT6A-72-14498 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION OF POWER TURBINE STATOR HOUSING, SERVICE BULLETIN POWER TURBINE STATOR HOUSING P/N 3121524-01 OR 3043706-01 WELD REPAIRED (PER OHM DATED MAR 24/2014 IN ANOTHER FACILITY (NOT P&WC SERVICE CENTERS OR P&WC DOFS))						NOT APPLICABLE - N/A DUE TO P/N OF THE STATOR.
	20-MAR-2015	MOS HRS/MSC - ENC		31-MAR-2015 4227:39 5618			
SB	PT6A-72-14499 NO. 2 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
	01-MAY-2015	MOS HRS/MSC - ENC		06-MAY-2015 4253:14 5658			
SB A	PT6A-72-14499 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
	01-MAY-2015	MOS HRS/MSC - ENC		06-MAY-2015 4253:14 5658			
SB B	PT6A-72-14499 PART NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						COMPLIED WITH - N/A DUE TO S/N OF OIL DIPSTICK IS NOT LISTED IN TABLE 1 OF SB.
	01-MAY-2015	MOS HRS/MSC - ENC		06-MAY-2015 4253:14 5658			
SB	PT6A-72-14499 R1 NO. 2 ENGINE - INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
	19-AUG-2015	MOS HRS/MSC - ENC		26-AUG-2015 4319:02 5737			
SB PART A	PT6A-72-14499 R1 NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR INSPECTION / REPLACEMENT						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
	19-AUG-2015	MOS HRS/MSC - ENC		26-AUG-2015 4319:02 5737			
SB PART B	PT6A-72-14499 R1 NO. 2 ENGINE - ACCOMPLISH INSPECTION / REPLACEMENT OF ELECTRICAL OIL-LEVEL FILLER-CAP AND INDICATOR, SERVICE BULLETIN A VISUAL OIL LEVEL VERIFICATION UNTIL REPLACEMENT OF THE ELECTRIC OIL-LEVEL FILLER-CAP AND INDICATOR IS INSTALLED						NOT APPLICABLE - N/A DUE TO REV 0 PERFORMED 06/05/2015.
	19-AUG-2015	MOS HRS/MSC - ENC		26-AUG-2015 4319:02 5737			
SB	PT6A-72-14509 NO. 2 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						NOT APPLICABLE - N/A DUE TO ENGINE S/N.
	31-AUG-2015	MOS HRS/MSC - ENC		03-SEP-2015 4319:02 5737			

Master AD/SI Report

PIAGGIO P180 AVANTI EASA.A.059 S/N 1079 (SP-MXH): 5736HRS, 8761 AFL as of 11-Feb-2021

AIRCRAFT
All Bulletins with Compliance or Due
Report Date: 17-Feb-2021

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PT6A-72-14509 R3	NO. 2 ENGINE - REPLACEMENT OF OVERSPEED GOVERNOR WASHER, SERVICE BULLETIN						COMPLIED WITH
19-OCT-2016		MOS		05-JUN-2018			
		HRS/MSC -		4729:58			
		ENC		6282			
SB PT6A-72-14603 R18	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
13-SEP-2012		MOS		23-DEC-2012			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14603 R19	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH - FOR ENGINES RK0103/4 AND RK0198/9 NO CHANGE IN THIS REV. ARE INCLUDE.
26-SEP-2012		MOS		03-MAR-2013			
		HRS/MSC -		3706:50			
		ENC		4821			
SB PT6A-72-14603 R22	NO. 2 ENGINE - OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY, SERVICE BULLETIN					RECOMMENDED	COMPLIED WITH
12-DEC-2013		MOS		27-NOV-2014			
		HRS/MSC -		4090:55			
		ENC		5396			
SPB 60 R1	NO. 2 ENGINE - TUBE FLANGED OIL FILLER OPTIONS - INTRDUCTION OF, SPARE PART BULLETIN						DEFERRED
		MOS		15-APR-2013			
		HRS/MSC A/R		3748:05			
		ENC		4881			
SPB 70 R1	NO. 2 ENGINE - OIL FILLER TUBE - REPLACEMENT OF, SPARE PART BULLETIN						DEFERRED
		MOS		15-APR-2013			
		HRS/MSC A/R		3748:05			
		ENC		4881			